


- Measurement: temperature, resistance, standard signals.
- 3-colour display (14 mm high), programmable in 3 ranges of the measured value.
- Meter programming from keyboard or through the RS-485 interface by means of the free LP Config program.
- 4 alarm outputs with signaling on LED diodes, working in 6 different modes.
- Conversion of any measured value into an analog signal 0/4...20 mA or 0...10 V.
- Storage of minimal and maximal values for all measured quantities.
- Supply of object transducers (ver. N30U 1XXXXXXX).
- 21-point individual characteristic for the measured value



## **Sifam Tinsley Instrumentation Inc.**

Address: 3105 Creekside Village Dr, Unit 801, Kennesaw, GA 30144

Tel.: 800-879-6171 | E-mail: info@sifamtinsley.com | Web: www.sifamtinsley.com